Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S79	44407	"intake manifold"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/02/14 17:04
S80	37794	tank with (vent venting ventilation vent\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/02/14 17:05
S81	344883	pressure with different\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/02/14 17:05
S82	1904442	error fault failure	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/02/14 17:08
S83	2285	73/118.1.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/02/14 17:08
S84	11	S79 & S80 & S81 & S82 & S83	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/02/14 17:08

, ∢.

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	3137	crankcase with (vent\$4 venting ventilation)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/02/14 19:36
L2	344883	pressure with different\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/02/14 19:37
L3	1904442	error fault failure	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/02/14 19:37
L4	2285	73/118.1.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/02/14 19:37
L5	2	L2 & 1 & L3 & L4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/02/14 19:37